


Layout Sketch of the Aircraft Plant in Chkalov



Scale about 1:10,000

Legend:

- 1 Airfield
- 2 Final assembly hall (cell lobbies)
- 3 Workshop
- 4 Transformer station
- 5 Two-story partial assembly hall. On the ground floor production of wings and tail assemblies was going on, while laboratories and small workshops were on the upper floor
- 6 Kitchen
- 7 Spur track
- 8 To